IMPORTANT

Weatheradio with Alert

Cat. No. 12-251

If a single dash appears on your Weatheradio's display after initial setup, you must re-program the broadcast frequency and FIPS codes. This might occur if AC power is disconnected and backup battery power is low (for example, after a power outage). Follow the instructions in "Programming the Weatheradio" on Page 16 of your Owner's Manual.

© 2000 Tandy Corporation. All Rights Reserved. RadioShack and RadioShack.com are trademarks used by Tandy Corporation.

RadioShack
A Division of Tandy Corporation
Fort Worth, Texas 76102

05A00 Printed in China

© 1999 Tandy Corporation. All Rights Reserved. RadioShack is a registered trademark used by Tandy Corporation.